




















XEV1Kxx
Quick start




-  x 4
-  x 2
-  x 8
-  x 4
-  x 4
-  x 4
-  x 1
T25S
- 
- 
-  x 6






Ø 8




3




Torx T30




4




5



6



1



16,5 mm

